

ABSTRACT

A method of forming an interface between components having different rates of volumetric expansion includes forming an interface surface of the interface with respect to a center of growth such that slippage occurs at the interface between the components during volumetric expansion.